
Proposed Subdivision
Brush Creek Estate -
Precinct 2, Stage 6B
Site Classification

Watalong Way,
Edgeworth

NEW18P-0170C-AD
1 September 2022



LABORATORY (NSW) PTY LTD

1 September 2022

McCloy Edgeworth Pty Ltd
Suite 2, Ground Floor, 317 Hunter Street
NEWCASTLE NSW 2300

Attention: Mr Bryson Cox

Dear Sir


**RE: PROPOSED SUBDIVISION - BRUSH CREEK ESTATE – PRECINCT 2, STAGE 6B
WATALONG WAY, EDGEWORTH
SITE CLASSIFICATION TO AS2870-2011 (LOTS 617 TO 626)**

Please find enclosed our Geotechnical Assessment report for Lots 617 to 626 within Precinct 2, Stage 6B of the Brush Creek Estate, located off Watalong Way, Edgeworth.

The report includes recommendations on site classification in accordance with AS2870-2011, 'Residential Slabs and Footings' following the completion of site regrading earthworks.

If you have any questions regarding this report, please do not hesitate to contact Ben Bunting, Shannon Kelly or the undersigned.

For and on behalf of Qualtest Laboratory (NSW) Pty Ltd



Jason Lee
Principal Geotechnical Engineer

Table of Contents:

1.0	Introduction	1
2.0	Desktop Study	1
3.0	Field Work	1
4.0	Site Description	2
4.1	Site Regrade Works.....	2
4.2	Surface Conditions	3
4.3	Subsurface Conditions.....	4
5.0	Laboratory Testing	7
6.0	Site Classification to AS2870-2011.....	8
7.0	Limitations.....	9

Attachments:

Figure AD1:	Site Plan and Approximate Test Locations
Appendix A:	Results of Field Investigations
Appendix B:	Results of Laboratory Testing
Appendix C:	CSIRO Sheet BTF 18

1.0 Introduction

Qualtest Laboratory NSW Pty Ltd (Qualtest) is pleased to present this geotechnical report on behalf of McCloy Edgeworth Pty Ltd (McCloy), for Precinct 2, Stage 6B, of the Brush Creek Estate, located off Watalong Way, Edgeworth.

Based on the brief and drawings provided by the client, Stage 6B is understood to include ten residential allotments (Lots 617 to 626), as shown on the attached Figure AD1.

The scope of work for the geotechnical investigation included providing site classification with respect to reactive soils, in accordance with the requirements of AS2870-2011 '*Residential Slabs and Footings*', following completion of site regrade works.

This report presents the results of the field work investigations and laboratory testing, and provides recommendations for the scope outlined above.

2.0 Desktop Study

The scope of work has included a review of the following reports completed by Qualtest:

- Site Classification, 'Proposed Subdivision, Brush Creek Estate – Precinct 2, Stage 6A, Transfield Avenue, Edgeworth, (Report Reference: NEW18P-0170C-AB.Rev1, dated 10 March 2021);
- Level 1 Site Regrade Assessment Report, 'Proposed Subdivision of Brush Creek Estate – Stage 6A, Edgeworth, (Report Reference: NEW20P-0093A-AA, dated 4 December 2020);
- Geotechnical Assessment, 'Proposed Subdivision, Brush Creek Estate – Precinct 2, Transfield Avenue, Edgeworth, (Report Reference: NEW18P-0170A-AA.Rev1, dated 4 March 2020); and,
- Geotechnical Investigation, 'Proposed Edgeworth Gravity Sewer Main' – Patterson Street to Minmi Road, Edgeworth, (Report Reference: NEW18P-0076-AB, dated 19 June 2018).

This report includes a summary of selected results from the previous reports. Reference should be made to the reports outlined above for further details of site description, subsurface conditions, field work conducted, engineering logs of test pits / boreholes, laboratory testing results, site supervision and density testing carried out.

3.0 Field Work

Field work investigations was carried out on 12 August 2022 and comprised of:

- DBYD search, review of plans, and visual check of proposed test locations for the presence of underground services;
- Site walkover to make observations of surface features at the property and in the immediate surrounding area;
- Drilling of eleven (11 no.) boreholes (BH617B to BH625B, BH626B-A and BH626B-B) using a 2.7 tonne excavator equipped with a 300mm diameter auger attachment. Boreholes were terminated at depths of between 0.20m and 2.50m;
- Undisturbed samples (U50 tubes) were taken for subsequent laboratory testing; and,
- Boreholes were backfilled with the excavation spoil and compacted using the excavator auger and tracks.

Investigations were carried out by an experienced Geotechnical Engineer from Qualtest who located the boreholes, carried out the sampling and testing, produced field logs of the boreholes, and made observations of the site surface conditions.

Engineering logs of the boreholes are presented in Appendix A. Approximate borehole locations are shown on the attached Figure AD1. Boreholes were located in the field by handheld GPS and relative to existing site features including topographic features, lot boundaries, existing developments and trees.

4.0 Site Description

4.1 Site Regrade Works

Site re-grading for Stage 6A & 6B bulk earthworks was conducted between 8 October 2020 and 4 November 2020. Re-grading works consisted of the removal of unsuitable materials, blending of Colluvium materials with site won Residual and stockpiled materials, along with cutting and filling activities to bring proposed residential lots within Stage 6A & 6B to design finish levels.

Re-grade works performed during the Stage 6B bulk earthworks included filling within all or portions of Lot 623 (previously listed as Lot 617) and Lot 626. Regrade works within these lots consisted predominantly of the placement of fill to raise site levels for future home sites, current and future site service infrastructure, and proposed retaining wall structures.

Refer to attached Figure AD1 for the approximate extent of lot filling works for this stage of the development.

Prior to filling, re-grade areas were stripped of all topsoil and unsuitable material to expose the suitable natural foundation profile. Re-grade works then consisted of filling with approved site fill to design finish levels.

Filling was performed using site stockpiled material won from excavations cut and blended from around the site. The fill material could generally be described as mixtures of Residual (Cl-CH) Gravelly Sandy CLAY and Extremely Weathered (EW) Siltstone / Sandstone, medium to high plasticity, brown / yellow / orange in colour, with fine to coarse grained sand and gravel, which was blended with a pale to dark brown Silty SAND (Colluvium).

The depth of fill placed ranged in the order of 0.1m to about 2.4m, with the following approximate maximum depths within each lot area outlined below:

- Lot 623 (previously lot 617) – 0.3m; and,
- Lot 626 – 2.4m.

The fill was compacted in maximum lifts of 0.3m thickness. Any unsuitable or deleterious material within the fill was removed by hand or mechanical means prior to final compaction of the material.

As the geotechnical testing authority engaged for the project, Qualtest state that the re-grading works performed within Stage 6B (as shown on attached Figure AD1), was carried out to Level 1 criteria as defined in Clause 8.2 – Section 8, of AS3798-2007, “*Guidelines on Earthworks for Commercial and Residential Developments*”.

The recommendations of this report are based on the understanding that any existing lot re-grade works are limited to the controlled earthworks supervised by Qualtest, and placement of low reactivity topsoil material such that total depth of topsoil and uncontrolled fill does not exceed 0.4m. Qualtest should be informed without delay if additional earthworks are known to have been carried out.

At the time of the field investigations on 12 August 2022, several small fill stockpiles were present on a number of lots, including Lots 620, 621, 623 and 625. It is understood and assumed that the fill stockpiles will be removed prior to development on the lots.

4.2 Surface Conditions

The site comprises Precinct 2, Stage 6B of the proposed residential subdivision known as Brush Creek Estate, located off Watalong Way, Edgeworth, as shown on Figure AD1 attached.

The site is bounded to the south by Stage 6A, to the north and east by an electrical easement and bushland, and by Keylkeyl Close to the west preceding dense bushland. Photographs of the site taken on the day of the site investigations are shown below.



Photograph 1: From near north-western corner of Lot 617, facing southeast.



Photograph 2: From near north-western corner of Lot 617, facing south.



Photograph 3: From near shared boundary of Lots 620 and 621, facing west.



Photograph 4: From near shared boundary of Lots 620 and 621, facing east.



Photograph 5: From eastern boundary of Lot 623, facing west.



Photograph 6: From eastern boundary of Lot 624, facing west.



Photograph 7: From north-eastern corner of Lot 625, facing west.



Photograph 8: From north-eastern corner of Lot 625, facing east. Lot 626 in background.

4.3 Subsurface Conditions

Reference to the 1:100,000 Newcastle Coalfield Regional Geology Series Sheet 9231 indicates the site to be underlain by the Adamstown Subgroup of the Newcastle Coal Measures, which are characterised by Conglomerate, Sandstone, Siltstone, Coal and Tuff rock types.

Table 1 presents a summary of the typical soil and rock types encountered at borehole locations during the field investigation, divided into representative geotechnical units.

Table 2 contains a summary of the distribution of the geotechnical units at the test locations.

TABLE 1 – SUMMARY OF GEOTECHNICAL UNITS AND SOIL / ROCK TYPES

Unit	Soil Type	Description
1A	FILL – MULCH AND TOPSOIL	Mixtures of Tree Mulch and Unit 1B: FILL-TOPSOIL materials, majority comprising of mulch.
1B	FILL – TOPSOIL	Sandy CLAY – generally low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, with some sticks.
1C	FILL – CONTROLLED	Gravelly Sandy CLAY – medium plasticity, pale grey and pale orange-brown to pale brown / brown, fine to coarse grained sand, fine to coarse grained (mostly fine to medium grained) rounded to sub-angular gravel. Sandy CLAY – low to medium plasticity, grey to dark grey, fine to coarse grained sand.
2	SLOPEWASH / COLLUVIUM	Not encountered within the current investigation.
3	ALLUVIUM	Not encountered within the current investigation.
4	RESIDUAL SOIL	Sandy CLAY, Gravelly Sandy CLAY – medium to high plasticity, pale orange-brown and grey, fine to coarse grained sand, fine to medium grained sub-rounded to angular gravel. Clayey Sandy GRAVEL – fine to medium grained, rounded to sub-rounded, pale grey-brown with some pale brown, fine to coarse grained sand, fines of medium plasticity.
5	EXTREMELY WEATHERED (XW) ROCK with soil properties	Pebbly Sandstone, Sandstone; breaks down into Clayey SAND – fine to coarse grained, pale orange-brown to pale brown with some pale grey to white, fines of low plasticity. Sandstone; breaks down into Sandy CLAY – low to medium plasticity, pale orange-brown, fine to coarse grained sand.
6	HIGHLY WEATHERED (HW) ROCK	Pebbly SANDSTONE, CONGLOMERATE – fine to coarse grained sand matrix, fine to medium grained rounded to sub-angular clasts, pale brown to pale orange-brown, trace pale grey to white, estimated low to medium strength.

TABLE 2 – SUMMARY OF GEOTECHNICAL UNITS ENCOUNTERED AT TEST LOCATIONS

Location	Unit 1A Fill: Mulch and Topsoil	Unit 1B Fill: Topsoil	Unit 1C Fill: - Controlled	Unit 2 Slopewash / Colluvium	Unit 3 Alluvium	Unit 4 Residual Soil	Unit 5 XW Rock	Unit 6 HW Rock
	Depth (m)							
Current Investigation (August 2022)								
BH617B	-	0.00 - 0.40	-	-	-	0.40 - 0.65	0.65 - 0.80	0.80 - 1.60*
BH618B	-	0.00 - 0.35	-	-	-	0.35 - 0.80	0.80 - 1.10	1.10 - 1.20*
BH619B	-	0.00 - 0.30	-	-	-	0.30 - 0.80	0.80 - 1.00	1.00 - 1.10*
BH620B	-	0.00 - 0.30	-	-	-	0.30 - 0.45	-	0.45 - 0.60*
BH621B	-	0.00 - 0.10	-	-	-	-	-	0.10 - 0.50*
BH622B	-	0.00 - 0.15	-	-	-	-	-	0.15 - 0.30*
BH623B	0.00 - 0.10	-	-	-	-	-	-	0.10 - 0.20*
BH624B	0.00 - 0.20	-	-	-	-	-	0.20 - 0.40	0.40 - 0.50*
BH625B	0.00 - 0.15	-	-	-	-	0.15 - 0.30	-	0.30 - 0.40*
BH626B-A	0.00 - 0.20	-	-	-	-	-	-	0.20 - 0.30*
BH626B-B	0.00 - 0.20	-	0.20 - 2.50	-	-	-	-	-
Previous Investigation (Ref: NEW18P-0170C-AB.Rev1, 10 March 2021)								
BH610	0.00 - 0.02	0.02 - 0.15	-	-	-	0.15 - 0.45	-	0.45 - 0.46*
BH611	0.00 - 0.10	0.10 - 0.30	-	-	-	0.30 - 0.55	-	0.55 - 0.56*
BH614	0.00 - 0.05	0.05 - 0.25	-	-	-	0.25 - 0.50	-	0.50 - 0.51*
BH615	0.00 - 0.05	0.05 - 0.25	-	-	-	0.25 - 0.55	-	0.55 - 0.56*

Location	Unit 1A	Unit 1B	Unit 1C	Unit 2	Unit 3	Unit 4	Unit 5	Unit 6
	Fill: Mulch and Topsoil	Fill: Topsoil	Fill: - Controlled	Slopewash / Colluvium	Alluvium	Residual Soil	XW Rock	HW Rock
Depth (m)								
BH616	-	0.00 - 0.20	-	-	-	0.20 - 0.55	-	0.55 - 0.56*
BH619	0.00 - 0.05	0.05 - 0.24	-	-	-	0.24 - 0.55	-	0.55 - 0.56*
BH622	-	0.00 - 0.20	-	-	-	0.20 - 0.50	-	0.50 - 0.60*
BH625	-	0.00 - 0.20	0.20 - 1.80	1.80 - 2.50	-	2.50 - 2.60	-	-
Previous Investigation (Ref: NEW18P-0170AA-AA.Rev1, 4 March 2020) – Prior to site regrade works								
TPP25	-	0.00 - 0.20	-	0.20 - 0.40	-	0.40 - 0.65	-	0.65 - 1.00#
TPP27	-	0.00 - 0.30	-	-	-	0.30 - 0.60	-	0.60 - 0.85#
TPP28	-	0.00 - 0.20	-	0.20 - 0.40	-	-	0.40 - 1.00	1.00 - 1.30#
Previous Investigation (Ref: NEW18P-0076-AB, 19 June 2018) – Prior to site regrade works								
BH23	-	0.00 - 0.25	-	0.25 - 0.45	0.45 - 0.80	0.80 - 0.90	-	0.90 - 1.00*
Notes:	* = Practical refusal to refusal of 2.7 tonne excavator with auger attachment met on weathered rock. # = Practical refusal or refusal of 20 tonne excavator bucket met on weathered rock.							

Groundwater levels or inflows were not encountered in boreholes during the limited time that they remained open on the day of the field investigations.

It should be noted that groundwater conditions can vary due to rainfall and other influences including regional groundwater flow, temperature, permeability, recharge areas, surface condition, and subsoil drainage.

5.0 Laboratory Testing

Samples collected during the field investigations were returned to our NATA accredited Newcastle Laboratory for testing which comprised of:

- (4 no.) Shrink / Swell tests.

Results of the laboratory testing are presented in Appendix B, with a summary of the Shrink/Swell and Atterberg Limits test results presented in Table 3 and Table 4, respectively, which also includes results from previous testing on adjacent lots.

TABLE 3 – SUMMARY OF SHRINK/SWELL TESTING RESULTS

Location	Depth (m)	Material Description	I _{ss} (%)
Current Investigation (August 2022)			
BH617B	0.50 - 0.65	(CI) Gravelly Sandy CLAY	0.6
BH618B	0.45 - 0.60	(CH) Sandy CLAY	2.2
BH619B	0.35 - 0.50	(CH) Sandy CLAY	1.8
BH626B-B	0.50 - 0.80	FILL: (CI) Gravelly Sandy CLAY	0.6
Previous Investigation (Ref: NEW18P-0170C-AB.Rev1, 10 March 2021)			
BH614	0.30 – 0.45	(CI) Sandy CLAY	0.7
BH622	0.25 – 0.45	(CI) Gravelly Sandy CLAY	0.4
Previous Investigation (Ref: NEW18P-0170AA-AA.Rev1, 4 March 2020)			
TPP27	0.40 - 0.55	(CH) Sandy CLAY	2.9

TABLE 4 – SUMMARY OF ATTERBERG LIMITS TESTING RESULTS

Location	Depth (m)	Material Description	Liquid Limit (%)	Plastic Limit (%)	Plasticity Index (%)	Linear Shrinkage (%)
Previous Investigation (Ref: NEW18P-0170C-AB.Rev1, 10 March 2021)						
BH625	0.50 – 0.65	FILL: (CL) Gravelly Sandy CLAY	29	16	13	5.5
Previous Investigation (Ref: NEW18P-0170AA-AA.Rev1, 4 March 2020)						
TPP28	0.60 - 0.70	(CI) Gravelly Sandy CLAY	36	19	17	7.0

The results of the Shrink/Swell and Atterberg Limits laboratory testing indicate that the residual soils tested from the site generally contain fines of medium plasticity.

6.0 Site Classification to AS2870-2011

Based on the results of the field work, laboratory testing and site regrade works conducted, residential lots located within Precinct 2, Stage 6B of the Brush Creek Estate residential subdivision, as shown on the attached Figure AD1, are classified in their current condition in accordance with AS2870-2011 '*Residential Slabs and Footings*', as shown in Table 5.

TABLE 5 – SITE CLASSIFICATION TO AS2870-2011

Lot Numbers	Site Classification
617 to 625	M
626	H1

A characteristic free surface movement of 20mm to 40mm is estimated for the lots classified as **Class 'M'** in their existing condition.

A characteristic free surface movement of 40mm to 60mm is estimated for the lots classified as **Class 'H1'** in their existing condition.

The effects of changes to the soil profile by additional cutting and filling and the effects of past and future trees should be considered in selection of the design value for differential movement.

If site re-grading works involving cutting or filling are performed after the date of this assessment, the classification may change and further advice should be sought.

Footings for the proposed development should be designed and constructed in accordance with the requirements of AS2870-2011.

The classification presented above assumes that:

- All footings are founded in controlled fill (if applicable) or in the residual clayey soils or rock below all non-controlled fill, topsoil material and root zones, and fill under slab panels meets the requirements of AS2870-2011, in particular, the root zone must be removed prior to the placement of fill materials beneath slabs;
- The performance expectations set out in Appendix B of AS2870-2011 are acceptable, and that site foundation maintenance is undertaken to avoid extremes of wetting and drying;
- Footings are to be founded outside of or below all zones of influence resulting from existing or future service trenches;
- The constructional and architectural requirements for reactive clay sites set out in AS2870-2011 are followed;
- Adherence to the detailing requirement outlined in Section 5 of AS2870-2011 '*Residential Slabs and Footings*' is essential, in particular Section 5.6, '*Additional requirements for Classes M, H1, H2 and E sites*' including architectural restrictions, plumbing and drainage requirements; and,
- Site maintenance complies with the provisions of CSIRO Sheet BTF 18, "*Foundation Maintenance and Footing Performance: A Homeowner's Guide*", a copy of which is attached in Appendix C.

All structural elements on all lots should be supported on footings founded beneath all uncontrolled fill, layers of inadequate bearing capacity, soft/loose, wet or other potentially deleterious material.

If any localised areas of uncontrolled fill of depths greater than 0.4m are encountered during construction, footings should be designed in accordance with engineering principles for Class 'P' sites.

7.0 Limitations

The findings presented in the report and used as the basis for recommendations presented herein were obtained using normal, industry accepted geotechnical design practices and standards. To our knowledge, they represent a reasonable interpretation of the general conditions of the site.


The extent of testing associated with this assessment is limited to discrete test locations. It should be noted that subsurface conditions between and away from the test locations may be different to those observed during the field work and used as the basis of the recommendations contained in this report.

If subsurface conditions encountered during construction differ from those given in this report, further advice should be sought without delay.

Data and opinions contained within the report may not be used in other contexts or for any other purposes without prior review and agreement by Qualtest. If this report is reproduced, it must be in full.

If you have any further questions regarding this report, please do not hesitate to contact Ben Bunting, Shannon Kelly or the undersigned.


For and on behalf of Qualtest Laboratory (NSW) Pty Ltd.






Jason Lee
Principal Geotechnical Engineer

FIGURE AD1:

Site Plan and Approximate Test Locations



LEGEND:

-  Approximate borehole location
-  Approximate borehole / test pit location (previous investigations - Qualtest, 2018 to 2021)
-  Approximate location and extent of controlled filling

Based on sales plan prepared and provided by McCloy Group



Client:	MCCLOY EDGEWORTH PTY LTD	Drawing No:	FIGURE AD1
Project:	BRUSH CREEK - STAGE 6B	Project No:	NEW18P-0170C
Location:	TRANSFIELD AVENUE, EDGEWORTH	Scale:	N.T.S.
Title:	SITE PLAN AND APPROXIMATE TEST LOCATIONS	Date:	1/09/2022

APPENDIX A:

Results of Field Investigations



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH617B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered	U50 0.65m		0.5		CL	FILL-TOPSOIL: Sandy CLAY - low to medium plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, with some sticks.	M > W _p				FILL - TOPSOIL
				0.50m		CH	Gravelly Sandy CLAY - medium to high plasticity, pale orange-brown and grey, fine to coarse grained sand, fine to medium grained sub-rounded to angular gravel.					VSt
				0.65m		SC	Extremely Weathered Pebbly Sandstone with soil properties; breaks down into Clayey SAND - fine to medium grained, pale orange-brown to pale brown, fines of low plasticity, trace fine to medium grained rounded to sub-rounded gravel.	D - M	VD		EXTREMELY WEATHERED ROCK	
				1.0			CONGLOMERATE - fine to coarse grained sand matrix, fine to medium grained rounded to sub-angular clasts, pale brown to pale orange-brown, estimated low to medium strength.					HIGHLY WEATHERED ROCK
				1.20m			Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, estimated low to medium strength.	D				
1.60m												
				2.0			Hole Terminated at 1.60 m Practical Refusal					
				2.5								

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:55 10.03.00.09 Datgei.Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₃₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft <25 S Soft 25 - 50 F Firm 50 - 100 St Stiff 100 - 200 VSt Very Stiff 200 - 400 H Hard >400 Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH618B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations		
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result	
AD/T	Not Encountered	U50 0.60m		0.5		CL	FILL-TOPSOIL: Sandy CLAY - low to medium plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, with some sticks.	M > W _p					FILL - TOPSOIL
						CH	Sandy CLAY - medium to high plasticity, pale orange-brown, fine to coarse grained sand.	M ~ W _p	VSt	HP	380	RESIDUAL SOIL	
						SC	Extremely Weathered Pebbly Sandstone with soil properties; breaks down into Clayey SAND - fine to coarse grained, pale orange-brown to pale brown with some pale grey to white, fines of low plasticity, trace fine to medium grained rounded to sub-rounded gravel.	D - M	VD			EXTREMELY WEATHERED ROCK	
							CONGLOMERATE - fine to coarse grained sand matrix, fine to medium grained rounded to sub-rounded clasts, pale brown to pale orange-brown, estimated medium strength.	D				HIGHLY WEATHERED ROCK	
				1.20			Hole Terminated at 1.20 m Practical Refusal						

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:55 10.03.00.09 Datagel Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₃₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft <25 S Soft 25 - 50 F Firm 50 - 100 St Stiff 100 - 200 VSt Very Stiff 200 - 400 H Hard >400 Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH619B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
ADT	Not Encountered	0.35m				CL	FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, with some fine to medium grained angular to sub-rounded gravel, with some sticks.	M > W _p				FILL - TOPSOIL
		U50 0.50m			0.30m		Sandy CLAY - medium to high plasticity, pale orange-brown to pale brown, fine to coarse grained sand.			HP	380	RESIDUAL SOIL
					0.50m	CH	Pale orange-brown and pale grey to white.	M ~ W _p	VSt - H	HP	430	
					0.80m	CL	Extremely Weathered Sandstone with soil properties; breaks down into Sandy CLAY - low to medium plasticity, pale orange-brown, fine to coarse grained sand.	M < W _p	H	HP	500	EXTREMELY WEATHERED ROCK
			1.00m		1.10m		Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, trace pale grey to white, fine grained rounded to sub-rounded clasts, estimated low to medium strength.	D				HIGHLY WEATHERED ROCK
							Hole Terminated at 1.10 m Practical Refusal					

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:55 10.03.00.09 Datgel,Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₅₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft S Soft F Firm St Stiff VSt Very Stiff H Hard Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH620B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered			0.5		CL	FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, with some sticks.	M > W _p				FILL - TOPSOIL
						CI	Sandy CLAY - medium plasticity, pale brown to brown, fine to coarse grained sand, with some fine grained rounded gravel.	M < W _p	VSt		RESIDUAL SOIL / POSSIBLE FILL	
							CONGLOMERATE - fine to coarse grained sand matrix, fine to medium grained rounded to sub-angular clasts, pale brown to pale orange-brown, estimated low to medium strength. Estimated medium strength.	D		HIGHLY WEATHERED ROCK		
							Hole Terminated at 0.60 m Practical Refusal					

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:55 10.03.00.09 Datgel.Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₅₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft S Soft F Firm St Stiff VSt Very Stiff H Hard Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH621B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
ADT	Not Encountered			0.5		CL	0.10m FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained rounded to sub-angular gravel, with some sticks. Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, trace pale grey to white, fine grained rounded to sub-rounded clasts, estimated low to medium strength. 0.50m	M ^h W _p				FILL - TOPSOIL HIGHLY WEATHERED ROCK
							Hole Terminated at 0.50 m Practical Refusal					

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:55 10.03.00.09 Datgel.Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₃₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft S Soft F Firm St Stiff VSt Very Stiff H Hard Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH622B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered					CL	FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular to sub-rounded gravel, with some sticks.	M > W _p				FILL - TOPSOIL
							Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, trace pale grey to white, fine grained rounded to sub-rounded clasts, estimated low to medium strength.	D				HIGHLY WEATHERED ROCK
				0.5			Hole Terminated at 0.30 m Practical Refusal					
				1.0								
				1.5								
				2.0								
				2.5								

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:55 10.03.00.09 Datgel,Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₃₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft S Soft F Firm St Stiff VSt Very Stiff H Hard Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH623B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered					CL	MULCH & FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, dominated by mulch.	DM > w _p				MULCH and FILL-TOPSOIL
							Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, estimated low to medium strength. Hole Terminated at 0.20 m Practical Refusal					HIGHLY WEATHERED ROCK
				0.5								
				1.0								
				1.5								
				2.0								
				2.5								

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:56 10.03.00.09 Datgel,Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₃₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft S Soft F Firm St Stiff VSt Very Stiff H Hard Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH624B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
ADT	Not Encountered			0.5		CL	MULCH & FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, dominated by mulch.	M > W _p				MULCH and FILL-TOPSOIL
						SC	Extremely Weathered Pebbly Sandstone with soil properties; breaks down into Clayey SAND - fine to coarse grained, pale orange-brown to pale brown, fines of low plasticity, trace fine to medium grained rounded to sub-rounded gravel.	D - M	VD		EXTREMELY WEATHERED ROCK	
							Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, estimated low to medium strength.	D			HIGHLY WEATHERED ROCK	
							Hole Terminated at 0.50 m Practical Refusal					

LEGEND:

Water

- Water Level (Date and time shown)
- Water Inflow
- Water Outflow

Strata Changes

- Gradational or transitional strata
- Definitive or distinct strata change

Notes, Samples and Tests

- U₃₀ 50mm Diameter tube sample
- CBR Bulk sample for CBR testing
- E Environmental sample (Glass jar, sealed and chilled on site)
- ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled)
- B Bulk Sample

Field Tests

- PID Photoionisation detector reading (ppm)
- DCP(x-y) Dynamic penetrometer test (test depth interval shown)
- HP Hand Penetrometer test (UCS kPa)

Consistency		UCS (kPa)	Moisture Condition	
VS	Very Soft	<25	D	Dry
S	Soft	25 - 50	M	Moist
F	Firm	50 - 100	W	Wet
St	Stiff	100 - 200	W _p	Plastic Limit
VSt	Very Stiff	200 - 400	W _L	Liquid Limit
H	Hard	>400		
Fb	Friable			

Density		Density Index	
V	Very Loose	<15%	
L	Loose	15 - 35%	
MD	Medium Dense	35 - 65%	
D	Dense	65 - 85%	
VD	Very Dense	85 - 100%	

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:56 10.03.00.09 Datgel.Lab and In Situ Tool



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH625B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered					CL 0.15m GC 0.30m 0.40m	<p>MULCH & FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, dominated by mulch.</p> <p>Clayey Sandy GRAVEL - fine to medium grained, rounded to sub-rounded, pale grey-brown with some pale brown, fine to coarse grained sand, fines of medium plasticity.</p> <p>CONGLOMERATE - fine to coarse grained sand matrix, fine to medium grained rounded to sub-angular clasts, pale brown to pale orange-brown, estimated low to medium strength.</p> <p>Hole Terminated at 0.40 m Practical Refusal</p>	M > Wp M D				<p>MULCH and FILL-TOPSOIL</p> <p>RESIDUAL SOIL / EXTREMELY WEATHERED ROCK</p> <p>HIGHLY WEATHERED ROCK</p>
				0.5 1.0 1.5 2.0 2.5								

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:56 10.03.00.09 Datgeel Lab and In Situ Tool

LEGEND: Water Water Level (Date and time shown) Water Inflow Water Outflow Strata Changes Gradational or transitional strata Definitive or distinct strata change	Notes, Samples and Tests U ₃₀ 50mm Diameter tube sample CBR Bulk sample for CBR testing E Environmental sample (Glass jar, sealed and chilled on site) ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled) B Bulk Sample	Consistency VS Very Soft S Soft F Firm St Stiff VSt Very Stiff H Hard Fb Friable	UCS (kPa) <25 25 - 50 50 - 100 100 - 200 200 - 400 >400	Moisture Condition D Dry M Moist W Wet W _p Plastic Limit W _L Liquid Limit
	Field Tests PID Photoionisation detector reading (ppm) DCP(x-y) Dynamic penetrometer test (test depth interval shown) HP Hand Penetrometer test (UCS kPa)	Density V Very Loose L Loose MD Medium Dense D Dense VD Very Dense	Density Index <15% Density Index 15 - 35% Density Index 35 - 65% Density Index 65 - 85% Density Index 85 - 100%	



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH626B-A
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered					CL	MULCH & FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, dominated by mulch.	M > W _p				MULCH and FILL-TOPSOIL
							Pebbly SANDSTONE - fine to coarse grained, pale brown to pale orange-brown, estimated medium strength.	D				HIGHLY WEATHERED ROCK
				0.5			Hole Terminated at 0.30 m Practical Refusal					
				1.0								
				1.5								
				2.0								
				2.5								

LEGEND:
Water
 Water Level (Date and time shown)
 Water Inflow
 Water Outflow
Strata Changes
 Gradational or transitional strata
 Definitive or distinct strata change

Notes, Samples and Tests
U₃₀ 50mm Diameter tube sample
CBR Bulk sample for CBR testing
E Environmental sample (Glass jar, sealed and chilled on site)
ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled)
B Bulk Sample
Field Tests
PID Photoionisation detector reading (ppm)
DCP(x-y) Dynamic penetrometer test (test depth interval shown)
HP Hand Penetrometer test (UCS kPa)

Consistency
VS Very Soft
S Soft
F Firm
St Stiff
VSt Very Stiff
H Hard
Fb Friable
Density
V Very Loose
L Loose
MD Medium Dense
D Dense
VD Very Dense

UCS (kPa)
<25
25 - 50
50 - 100
100 - 200
200 - 400
>400
Moisture Condition
D Dry
M Moist
W Wet
W_p Plastic Limit
W_L Liquid Limit
Density Index <15%
Density Index 15 - 35%
Density Index 35 - 65%
Density Index 65 - 85%
Density Index 85 - 100%



ENGINEERING LOG - BOREHOLE

CLIENT: McCLOY EDGEWORTH PTY LTD
PROJECT: BRUSH CREEK SUBDIVISION - STAGE 6B
LOCATION: WATALONG WAY, EDGEWORTH

BOREHOLE NO: BH626B-B
PAGE: 1 OF 1
JOB NO: NEW18P-0170C
LOGGED BY: BB
DATE: 12/8/22

DRILL TYPE: 2.7 TONNE EXCAVATOR WITH AUGER
BOREHOLE DIAMETER: 300 mm

SURFACE RL:
DATUM:

Drilling and Sampling				Material description and profile information					Field Test		Structure and additional observations	
METHOD	WATER	SAMPLES	RL (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION: Soil type, plasticity/particle characteristics, colour, minor components	MOISTURE CONDITION	CONSISTENCY DENSITY	Test Type		Result
AD/T	Not Encountered	U50		0.50m	0.5	CL	MULCH & FILL-TOPSOIL: Sandy CLAY - low plasticity, dark brown, fine to coarse grained sand, trace fine to medium grained angular gravel, dominated by mulch.	M > W _p	St	HP	180	MULCH and FILL-TOPSOIL
							FILL: Gravelly Sandy CLAY - medium plasticity, pale grey and pale orange-brown to pale brown, fine to coarse grained sand, fine to coarse grained (mostly fine to medium grained) rounded to sub-angular gravel.					FILL - CONTROLLED
							FILL: Gravelly Sandy CLAY - medium plasticity, brown, fine to coarse grained sand, fine to coarse grained (mostly fine to medium grained) rounded to sub-angular gravel.					
							FILL: Sandy CLAY - low to medium plasticity, grey to dark grey, fine to coarse grained sand.					
				0.80m	1.0	CI						
				1.60m	1.5	CI						
				2.50m	2.0	CL						
					2.5		Hole Terminated at 2.50 m					

LEGEND:

Water

- Water Level (Date and time shown)
- Water Inflow
- Water Outflow

Strata Changes

- Gradational or transitional strata
- Definitive or distinct strata change

Notes, Samples and Tests

- U₃₀ 50mm Diameter tube sample
- CBR Bulk sample for CBR testing
- E Environmental sample (Glass jar, sealed and chilled on site)
- ASS Acid Sulfate Soil Sample (Plastic bag, air expelled, chilled)
- B Bulk Sample

Field Tests

- PID Photoionisation detector reading (ppm)
- DCP(x-y) Dynamic penetrometer test (test depth interval shown)
- HP Hand Penetrometer test (UCS kPa)

Consistency		UCS (kPa)	Moisture Condition
VS	Very Soft	<25	D Dry
S	Soft	25 - 50	M Moist
F	Firm	50 - 100	W Wet
St	Stiff	100 - 200	W _p Plastic Limit
VSt	Very Stiff	200 - 400	W _L Liquid Limit
H	Hard	>400	
Fb	Friable		
Density			
V	Very Loose		Density Index <15%
L	Loose		Density Index 15 - 35%
MD	Medium Dense		Density Index 35 - 65%
D	Dense		Density Index 65 - 85%
VD	Very Dense		Density Index 85 - 100%

OT.LIB.1.1.GLB.Log_NON-CORED BOREHOLE - TEST PIT_NEW18P-0170C-AD - LOGS.GPJ <-DrawingFile> 31/08/2022 18:56 10.03.00.09 Datagel Lab and In Situ Tool

APPENDIX B:

Results of Laboratory Testing


Report No: SSI:NEW22W-2815-S01

Issue No: 1

Shrink Swell Index Report

Client: McCloy Project Management Pty Ltd
 PO Box 2214
 Dangar NSW 2309

Project No.: NEW18P-0170C
Project Name: Brush Creek Subdivision - Precinct 2, Stage 6A
Project Location: Transfield Avenue, Edgeworth



Accredited for compliance with ISO/IEC 17025-Testing. The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. Results provided relate only to the items tested or sampled.

Kyle Spencer
 Approved Signatory: Kyle Spencer
 (Geotechnician)
 NATA Accredited Laboratory Number: 18686
 Date of Issue: 30/08/2022

Sample Details


Sample ID: NEW22W-2815-S01
Sampling Method: The results outlined below apply to the sample as received
Material: Sandy CLAY
Source: On-Site Insitu
Specification: No Specification
Sample Location: BH617B - (0.50 - 0.65m)
Date Tested: 19/08/2022

Date Sampled: 12/08/2022
Date Submitted: 12/08/2022

Swell Test		AS 1289.7.1.1
Swell on Saturation (%):	-0.8	
Moisture Content before (%):	17.1	
Moisture Content after (%):	23.1	
Est. Unc. Comp. Strength before (kPa):	>600	
Est. Unc. Comp. Strength after (kPa):	160	

Shrink Test		AS 1289.7.1.1
Shrink on drying (%):	1.1	
Shrinkage Moisture Content (%):	18.1	
Est. inert material (%):	4%	
Crumbling during shrinkage:	Nil	
Cracking during shrinkage:	Moderate	

Shrink Swell



Shrink Swell Index - Iss (%): 0.6

Comments


Report No: SSI:NEW22W-2815-S02

Issue No: 1

Shrink Swell Index Report

Client: McCloy Project Management Pty Ltd
 PO Box 2214
 Dangar NSW 2309

Project No.: NEW18P-0170C
Project Name: Brush Creek Subdivision - Precinct 2, Stage 6A
Project Location: Transfield Avenue, Edgeworth



Accredited for compliance with ISO/IEC 17025-Testing. The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. Results provided relate only to the items tested or sampled.

Kyle Spencer
 Approved Signatory: Kyle Spencer
 (Geotechnician)
 NATA Accredited Laboratory Number: 18686
 Date of Issue: 30/08/2022


Sample Details

Sample ID: NEW22W-2815-S02
Sampling Method: The results outlined below apply to the sample as received
Material: Sandy CLAY
Source: On-Site Insitu
Specification: No Specification
Sample Location: BH618B - (0.45 - 0.60m)
Date Tested: 19/08/2022

Date Sampled: 12/08/2022
Date Submitted: 12/08/2022

Swell Test AS 1289.7.1.1		Shrink Test AS 1289.7.1.1	
Swell on Saturation (%):	-0.4	Shrink on drying (%):	3.9
Moisture Content before (%):	26.5	Shrinkage Moisture Content (%):	26.0
Moisture Content after (%):	28.9	Est. inert material (%):	2%
Est. Unc. Comp. Strength before (kPa):	280	Crumbling during shrinkage:	Nil
Est. Unc. Comp. Strength after (kPa):	280	Cracking during shrinkage:	Minor

Shrink Swell



Shrink Swell Index - Iss (%): 2.2

Comments

Report No: SSI:NEW22W-2815-S03

Issue No: 1

Shrink Swell Index Report

Client: McCloy Project Management Pty Ltd
 PO Box 2214
 Dangar NSW 2309

Project No.: NEW18P-0170C
Project Name: Brush Creek Subdivision - Precinct 2, Stage 6A
Project Location: Transfield Avenue, Edgeworth



Accredited for compliance with ISO/IEC 17025-Testing. The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. Results provided relate only to the items tested or sampled.

D. Cullen
 Approved Signatory: Dane Cullen
 (Materials Manager)
 NATA Accredited Laboratory Number: 18686
 Date of Issue: 30/08/2022


Sample Details

Sample ID: NEW22W-2815-S03
Sampling Method: The results outlined below apply to the sample as received
Material: Sandy CLAY
Source: On-Site Insitu
Specification: No Specification
Sample Location: BH619B - (0.35 - 0.50m)
Date Tested: 19/08/2022

Date Sampled: 12/08/2022
Date Submitted: 12/08/2022

Swell Test AS 1289.7.1.1		Shrink Test AS 1289.7.1.1	
Swell on Saturation (%):	0.0	Shrink on drying (%):	3.3
Moisture Content before (%):	24.1	Shrinkage Moisture Content (%):	23.5
Moisture Content after (%):	24.8	Est. inert material (%):	3%
Est. Unc. Comp. Strength before (kPa):	450	Crumbling during shrinkage:	Nil
Est. Unc. Comp. Strength after (kPa):	400	Cracking during shrinkage:	Minor

Shrink Swell



Shrink Swell Index - Iss (%): 1.8

Comments

Report No: SSI:NEW22W-2815-S04

Issue No: 1


Shrink Swell Index Report

Client: McCloy Project Management Pty Ltd
 PO Box 2214
 Dangar NSW 2309

Project No.: NEW18P-0170C

Project Name: Brush Creek Subdivision - Precinct 2, Stage 6A

Project Location: Transfield Avenue, Edgeworth



Accredited for compliance with ISO/IEC 17025-Testing. The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. Results provided relate only to the items tested or sampled.

Kyle Spencer
 Approved Signatory: Kyle Spencer
 (Geotechnician)
 NATA Accredited Laboratory Number: 18686
 Date of Issue: 30/08/2022

Sample Details

Sample ID: NEW22W-2815-S04

Sampling Method: The results outlined below apply to the sample as received

Material: Sandy CLAY

Source: On-Site Insitu

Specification: No Specification

Sample Location: BH626B-B - (0.5 - 0.8m)


Date Tested: 19/08/2022

Date Sampled: 12/08/2022

Date Submitted: 12/08/2022

Swell Test AS 1289.7.1.1		Shrink Test AS 1289.7.1.1	
Swell on Saturation (%):	-1.5	Shrink on drying (%):	1.1
Moisture Content before (%):	14.7	Shrinkage Moisture Content (%):	14.9
Moisture Content after (%):	16.2	Est. inert material (%):	2%
Est. Unc. Comp. Strength before (kPa):	490	Crumbling during shrinkage:	Nil
Est. Unc. Comp. Strength after (kPa):	420	Cracking during shrinkage:	Moderate

Shrink Swell



Shrink Swell Index - Iss (%): 0.6

Comments

APPENDIX C:

CSIRO Sheet BTF 18

**Foundation Maintenance and Footing
Performance: A Homeowner's Guide**

Foundation Maintenance and Footing Performance: A Homeowner's Guide



CSIRO

BTF 18
replaces
Information
Sheet 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

Soil Types

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870, the Residential Slab and Footing Code.

Causes of Movement

Settlement due to construction

There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take place because of the expulsion of moisture from the soil or because of the soil's lack of resistance to local compressive or shear stresses. This will usually take place during the first few months after construction, but has been known to take many years in exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology File 19 (BTF 19) deals with these problems.

Erosion

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

Saturation

This is particularly a problem in clay soils. Saturation creates a bog-like suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume – particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- Significant load increase.
- Reduction of lateral support of the soil under the footing due to erosion or excavation.
- In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

GENERAL DEFINITIONS OF SITE CLASSES

Class	Foundation
A	Most sand and rock sites with little or no ground movement from moisture changes
S	Slightly reactive clay sites with only slight ground movement from moisture changes
M	Moderately reactive clay or silt sites, which can experience moderate ground movement from moisture changes
H	Highly reactive clay sites, which can experience high ground movement from moisture changes
E	Extremely reactive sites, which can experience extreme ground movement from moisture changes
A to P	Filled sites
P	Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways:

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

Unevenness of Movement

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- Differing compaction of foundation soil prior to construction.
- Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sun's heat is greatest.

Effects of Uneven Soil Movement on Structures

Erosion and saturation

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the mortar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpend).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay

Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of cornice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.

Trees can cause shrinkage and damage



As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptoms do not simply reflect the original cause. A common symptom is binding of doors on the vertical member of the frame.

Effects on full masonry structures

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred.

The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation cause a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken rubble is used as fill. Water that runs along these trenches can be responsible for serious erosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem.

Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

- Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870.

AS 2870 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

Prevention/Cure

Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.

It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.


Protection of the building perimeter

It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving

CLASSIFICATION OF DAMAGE WITH REFERENCE TO WALLS

Description of typical damage and required repair	Approximate crack width limit (see Note 3)	Damage category
Hairline cracks	<0.1 mm	0
Fine cracks which do not need repair	<1 mm	1
Cracks noticeable but easily filled. Doors and windows stick slightly	<5 mm	2
Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weathertightness often impaired	5–15 mm (or a number of cracks 3 mm or more in one group)	3
Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window and door frames distort. Walls lean or bulge noticeably, some loss of bearing in beams. Service pipes disrupted	15–25 mm but also depend on number of cracks	4



- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order.

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

Existing trees

Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

should extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick vent bases.

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthenware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paving on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

Condensation

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

Warning: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by

CSIRO PUBLISHING PO Box 1139, Collingwood 3066, Australia

Freecall 1800 645 051 Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au

Email: publishing.sales@csiro.au

© CSIRO 2003. Unauthorised copying of this Building Technology file is prohibited