

Disclaimer
The BALS as depicted on this map have been determined by vegetation within 100m of Stage 5 at the time of the assessment in January 2020. It should be noted that conditions may change over time, that may result in different BALs for the site.
Although every care has been taken in the preparation of this map the author accepts no responsibility for any misprints, errors, omissions, inaccuracies in these maps or damages resulting from the use of this information.

Note:
Boundaries are not survey accurate.
Although all reasonable care has been taken to ensure the information shown on this map is up to date and accurate, no guarantee is given that the information portrayed is free from error or omission. Please verify the accuracy of all information prior to use.

Legend
- Subject Site
- 100m Buffer
- Temporary APZ until Stage 6 occurs
- 20m APZ
- 4m Setback
- Open Forest
- Managed Land
- BAL 40
- BAL 29
- BAL 19
- BAL 12.5

FIGURE 4-1: BAL MAP

Ref No 2550

CLIENT	Client
SITE DETAILS	Stages 5 Transfield Avenue Edgeworth
DATE	21 May 2020

NORTH

0 25 50 100

SCALE 2000 @ A3

PIXELDRAFTING

Firebird ecoSultants Pty Ltd
ABN - 16 105 985 993
Level 1, 146 Hunter Street, Newcastle NSW 2300
P O Box 354 Newcastle NSW 2300

firebird

DISCLAIMER

This docment and the information shown shall remain the property of Firebird ecoSultants Pty Ltd. The document may only be used for the purpose for which it was supplied and in accordance with the terms of engagement for the commission. Unauthorised use of this document in any way is prohibited